






6. HANDLE STAGE WITH CLEAN GLOVES, IF CLEANING IS REQUIRED, A LINT FREE CLOTH DAMPED WITH IPA CAN BE USED TO WIPE SURFACE.

**!UNCONTROLLED COPY!
!DO NOT PRINT AND STORE!**

COPYRIGHT© 2017 PRIOR SCIENTIFIC - QUEENSGATEALL RIGHTS RESERVED, NO UNAUTHORISED DUPLICATION OR MANUFACTURE PERMITTED

	GENERAL TOLERANCES UNLESS OTHERWISE STATED: X ± 0.50mm XX ± 0.20mm XX ± 0.1mm XXXX ± 0.05mm ANGULAR ± 0.5°		Drawing no. QG-0213-IN-100001 Title / Description NPS-XY-100D INSTALLATION DRAWING		Issue 1 Date issue created 23-Aug-2017	
			Material ALUMINIUM		Finish CLEAN	
	Issue created by JC		Approved by LD		Scale 1:1	Sheet no. Sheet 1 OF 1